

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

CU487 VS 5762
SW WEST 24TH /SURF AVE
1/2-1 BROOKLYN, NY
0.756 mi.
3991 ft. Site 6 of 7 in cluster CU

NY Spills S106736172
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: VS 5762
Address: WEST 24TH /SURF AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0410239 / 2005-04-22
Facility ID: 0410239
Facility Type: ER
DER Facility ID: 270381
Site ID: 335158
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2004-12-14
Investigator: SKARAKHA
Referred To: Not reported
Reported to Dept: 2004-12-15

CID: 444
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-12-15
Spill Record Last Update: 2005-04-22
Spiller Name: ERT DESK
Spiller Company: VS 5762
Spiller Address: WEST 24TH /SURF AVE
Spiller Company: 001
Contact Name: ERT DESK
DEC Memo: "e2mis 156570 12/14/05 - 0925 K. DAVIS REPORTS FINDING APPROX 3 PTS

OF AN UNKNOWN OIL ON APPROX 3000 GALS OF WATER IN VS5762 (FDR 11B09).
SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO SEWER
CONNECTIONS. NO SUMPS. NO MOVEMENT IN THE WATER. TRANSF WAS INSTALLED
2/2/94. HISTORICAL PCB COUNT IS 9 PPM DTD 5/7/95. OIL LEVEL IS 25+.
TEMP IS 30. TRANSFORMER IS PRESENTLY BEINBG PRESSURE TESTED. Lab
Sequence Number: 04-10380-001 - PCBs < 1 ppm UPDATE: 12/15/04 - 1500
D. BANKHEAD - ENV. OPS., REPORTS CLEANUP COMPLETED BY DOUBLE WASHING
STRUCTURE WITH BIO GEN 760. LIQUID WASTE REMOVED BY TANKER. SUMP
FOUND CEMENTED. TAG REMOVED."

Remarks: "3 pints unknown oil on 3000 gallons of water: no to 5 questions;
while cleaning up it filled up to fast, pending additional resources:
coned # 156570: coming off 24 hour clock"

All Materials:

Site ID: 335158
Operable Unit ID: 1097263
Operable Unit: 01
Material ID: 577236
Material Code: 0066A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported